			Potomac Manors				
LOT	BLOCK	FRONTAGE	ALIGNMENT	SIZE	SHAPE	WIDTH	LOT ARE
36			Pipestem		Pipestem	330	87555.6
27			Perpendicular	109,771.20	Irregular	300	
17			Pipestem	104 544 00	Pipestem		71438.4
5	A		Perpendicular	98,010.00		160	68824.8
6	A		Perpendicular		Rectangular	280	64033.2
	В		Perpendicular			220	55756.8
	В		Perpendicular		Rectangular	255	57499.2
30		<del></del>	Perpendicular		Rectangular	270	57063.0
29			Perpendicular		Rectangular	210	60112.8
28			Perpendicular	91,476.00		235	60548.4
8				88,426.80		250	50094.0
31	~~~		Perpendicular		Rectangular	240	55321.2
	<u>Б</u> А		Perpendicular		Rectangular	230	58806.0
12			Perpendicular		Rectangular	280	55756.8
			Perpendicular	91,476.00		225	62726.4
13			Perpendicular	136,342.80		220	87555.6
34			Perpendicular		Rectangular	200	65340.0
	D		Perpendicular	87,555.60		330	52707.6
	A	240	Perpendicular		Rectangular	250	54885.6
22			Perpendicular		Rectangular	280	55756.8
20			Perpendicular		Rectangular	260	52272.0
	A		Perpendicular	87,991.20	Rectangular	280	50094.0
18			Perpendicular	91,476.00		310	60112.8
21			Perpendicular		Rectangular	240	60984.0
20			Perpendicular	87,120.00		220	56192.4
35			Perpendicular	100,188.00	Rectangular	260	43995.6
32			Perpendicular	87,120.00	Irregular	370	47916.0
33			Perpendicular	87,991.20	Irregular	280	55756.8
23		518	Perpendicular	109,771.20	Irregular	300	43560.0
11			Perpendicular	97,574.40		280	54014.4
	В		Perpendicular	91,476.00	Rectangular	240	39639.6
11		226/255	Perpendicular	101,930.40		175	64468.8
10			Perpendicular		Rectangular	175	44866.8
12	4	294/350	Perpendicular		Rectangular	350	71438.4
10	4		Perpendicular	103,237.20		260	43560.0
			-		9		
osed L	ots	Takker to the 1998		To the second	le de la company	- Establish	12 (12 (12 (12 (12 (12 (12 (12 (12 (12 (
37			Perpendicular	91,476.00	Rectangular	240	59,677.2
38			Pipestem	117,612.00		400	74,052.0
39		260 F	Perpendicular	95,832.00	Rectangular	240	65,340.00

July 28, 2004

Maryland- National Capital Park & Planning Commission Subdivision Office, Development Review Division. 8787 Georgia Avenue, Silver Spring, Maryland 20910

Dear Sir or Madam

I received a letter from Witmer Associate, LLC, regarding the subdivision application (MNCP&PC No:1-05010, copy is enclosed). I am an owner of the house at Lot 35 (west of Lot37, 10701 Burbank Drive) and I am writing to you, as I have some concern about the use of the joint driveway during construction and after the completion of the subdivision.

Please let me explain the situation. The driveway has been the sole driveway to the existing house (10611 Burbank Drive) and is highlighted in the attached copy. This driveway branches off westwards to our side entrance crossing another driveway which probably belongs to Lot 36. The residents including us in Lot 35 has been using the driveway jointly based upon the legal document describing the easement for the use of the driveway ( a copy of the document is enclosed). We do not use this side entrance frequently but the use of the driveway and side entrance is essential for delivery of fuels to our house. This is the entrance to have an access to oil and propane tanks. So, I would like to continue to use the joint driveway without interruption during the construction and after completion of the subdivision.


I sincerely hope that the owner of the property fully understands the situation and that I can maintain the easement to use the joint driveway. I would greatly appreciate it if you would let the owner be aware of this situation and my request.

Sincerely

23 III Junichi Kambayashi

10710 Burbank Drive, Potomac, MD 20854.

Home phone: 301 983 6315, Cell phone: 301 461 8479



## This **Beed**

Made this 18 day of October.

19 65, by and between

HERMAN SCHMIDT and LORRAINE G. SCHMIDT, HIS WIFE.

opk parties hereto of the first part, and

RALPH T. COMPTON and MARY B. COMPTON, HIS WIFE,

part ies hereto of the second part:

The United States,

the receipt of which is hereby acknowledged, the said part ies of the first part do \_\_\_\_ grant and convey unto the said part ies of the second part, in fee simple as TENANTS BY THE ENTIRETY, all that \_\_\_ piece \_\_ or parcel \_\_ of ground, with the improvements, casements and appurtenances thereunto belonging, situate, lying and being in the County of \_\_\_ Montgomery

State of Maryland, being part of the same land which the said Herman Schmidt, one of the part ies of the first part obtained from Albert Howard and Robert C. Pollock, Trustees,

by deed dated the - 20th — day of — July — , 19 45, recorded among the Land Records of said County in Liber No. — 974 — , at folio - 275 — , and being described as follows, to wit:

All of Lot numbered Nine (9), in Block lettered "B", in a subdivision known as "Section 1, POTOMAC MANORS": as per plat recorded in Plat Book No. 48, plat 3643, one of the Land Records for said Montgomery County, EXCEPTING, HOWEVER, that portion thereof heretofore conveyed by the parties of the first part to Ralph T. Compton and Ethel E. Compton (now deceased) by Deed dated the 29th of December, 1949, recorded in Liber 1335, at folio 225;

TOGETHER WITH AND SUBJECT TO an easement for use as a Joint Driveway by the parties of the second part, their heirs and assigns, in common with the Grantors, their heirs and assigns, within the following described property, to wit:-

"B", in said subdivision known as "Section 1, POTOMAC MANORS"; as per plat recorded in Plat Book No. 34, plat 2304, of said Land Records, said point being South 35 degrees 03 minutes 50 seconds West 111.29 feet from the most Easterly corner of said Lot 8, and running thence from said point of beginning along the Southeasterly side of said Lot 8, South 35 degrees 03 minutes 50 seconds West 200 feet to the beginning of a fillet curve leading into Burbank Drive, said curve being designated as No. 6 on said last-mentioned recorded plat; thence leaving Lot 8 and running with the limit of dedication of Burbank Drive, South 55 degrees 11 minutes 00 seconds East 30.01 feet; thence parallel with the Southeasterly line of said Lot 8, North 35 degrees 03 minutes 50 seconds East 199.35 feet; thence North 54 degrees 56 minutes 10 seconds West 30 feet to the place of beginning; the cost of maintenance of said Joint Driveway to be equally borne by each of the abutting property owners, their heirs and assigns;

