




Staff recommends that a sidewalk connection be provided between the bus stop and South Glen Road.

Staff recommends that the trail be aligned across Democracy Boulevard and that a striped crosswalk be provided.

T. CHURCH
2
T 1

E 1251233

Staff recommends that the end of Cranford Drive be realigned.

FALLS ROAD GOLF COURSE
(MANAGED BY M-NCPPC)

FALLS ROAD (MD 189)

BUS STOP PAD
(CONC.)

R=300'

WATER LINE

CONSTRUCTION

PROPOSED RIGHT OF WAY LINE

PROPOSED TEMPORARY CONSTRUCTION EASEMENT

CRANFORD DRIVE

BUS STOP PAD (HMA)

EXISTING RIGHT OF WAY LINE

AREA MACINTOSH WHITEWAY &
JEFFREY J. WHITEWAY
18567/0074
BLOCK 1, LOT 23

SHAHAB & G. RAVERTY
17596/0722
BLOCK 4, LOT 1

RES.

EXISTING RIGHT OF WAY LINE

E 1251300

LINE OF DIVISION

Attachment 7

